



# Details of Medium Vulnerable Areas to Flood (Rural - Firka Level)

## Vulnerable Areas

Firka Name : **Mulanur**  
 Block : **Mulanur**  
 Taluk : **Dharapuram**  
 District : **Tiruppur**

II. Details of Vulnerability area						
Type of Vulnerability in the area	Details of the area	Inundation level (ft) No. of days	Source of Flood	Name of Relief Centres	Street to be used escape to relief centre	Distance to relief centre (In Km)
1	2	3	4	5	6	7
Medium Vulnerability	Koneipatti	Below 3 Feet / 1 day	Nalathangal Odai	G.H.S. School, Ebugavalasu	Oddaichathram Road	12
I. Details of Contacts						
Name of the contract Details				Contact No		
Name of the Nodal Officer	Selvi Grace Pechuan, I.A.S., Sub Collector, Dharapuram.			Land line :04258-220216 Mobile No 9445000440		
Name of the Inter Department Team Leader	Thiru Ramesh Kumar , PD, DRDA, Tiruppur.			Mobile No:7373704212		
Nearest Police Station	Mulanur			Land Line : 04202-227233 Mobile No : 8300060602		
Nearest Fire & Rescue station	Dharapuram			Land Line :04258-220399 Mobile No 9445000565		
Name of the Tahk	Dharapuram			Land Line :04258-220345 Mobile No : 9445086353		



Note : Vulnerability Area Maps - Rural Areas - Firka wise and not more than 3 Locations in each map alone to be marked. if morethan 3 Location are there in the firka, additional maps to be prepared according to the numbers. (P.T.O)

III. Analysis of Medium Vulnerability (RURAL)		Details of First Responders			
Details of Medium Vulnerability	Place of Flooding		Name	Location	Contact No.
	Location 1		Location 1		
1	Sources of Flooding	Nallthangal Odai	1. Magesh Prabu 2.M.Pasupathy		9843240404 9786206084
2	Cause of Flooding (Breach / Overflow / Encroachment etc.,	Overflow	- -	Koneripatti	- -
3	Rainfall Received in that area (Heavy down pour data triggered the event with date).	20-10-2014 Railfall 200 mm	-		-
4	Relief centres operated to tide over the situation	Govt.Hr.Sec.School, Elugamvalasu			
5	Number of persons evacuated and house in relief camps	15 Family 20 Members			
6	Number of days Relief Camps was in operation.	One day			
7	Works taken up during current year.	-			
a)	Temporary Measures taken to restore damaged portions in case of breaches.	-			
b)	Permanent Measures taken to restore damaged portions in case of breaches.	-			
c)	Desilting activities under taken	As per G.O.Ms.No. 50 Desiltation work taken up			
8	Permanent Measures identified to be under taken to minimize the risk in area. (Diversion Canal Constructions of retaining wall, Conversion of pipe culvert to box culvert etc., )	Advance Release of Water			